

Art Hess Property Warwick Township Lancaster County, PA

The main branch of Lititz Run flows through a portion of the western part of Art Hess' property. Restoration efforts were undertaken in 1994-1995. After some regrading work was completed, 1,000 linear feet of stream were stabilized with rock. Several fish cover structures were installed. A spring on the property was diverted away from a manure storage area. The pipe now brings the spring's flow underground, where it discharges under a fish cover structure. Reseeding was also completed.

